



SL:

- 1) 1 St. Gehäuse Cito-QC, kpl. (550...)
- 4) 2 St. Doppelnippel cito 3/8x3/8, MS (510030)
- 5) 2 St. O-Ring cito in/out, 15x2,5 (502051)
- 6) 1 St. BG Eing.schlauch Vario (577031)
- 7) 1 St. BG Ausg.schlauch Vario (577032)
- 9) 1 St. Rohrsteckverschr., 90(506001),
- 15) 1 St. Bedienanleitung cito (545075)
- 16) 1 St. VK VHP/Uno inox/cito,i.Griff (610076)
- 17) 1 St. Kart.eins. cito für 610076 (610080)
- 18) 1 St. Kart.überstülper cito (605042)
- 21) 1St. DVB (620008)
- 22) 0,25 St. 4er-VK (610078)
- 23) 1 St O-Ring (502053)

**Arbeitsplan
auf Blatt 2**

1	erst.	15.1.16	Hanf
2	B1+B2; AP : BG.1.2/1.4 einschrumpfen	28.1.16	Hanf
3	T-St. in (6) neu	14.4.16	Hanf
4	oberen O-Ring tauschen	08.8.16	Bubke

**CITO-QC Basic,
Blatt 1**

120QC-BS3-B1

